



MS2510 Current Loop Receiver User Manual



Metal Samples Company

A Division of Alabama Specialty Products, Inc.

152 Metal Samples Rd., Munford, AL 36268 Phone: (256) 358-4202 Fax: (256) 358-4515

E-mail: msc@alspi.com Internet: www.metalsamples.com

Table of Contents

SECTION 1 – INTRODUCTION

Receiving the Instrument.....	3
Unpacking	3
Cleaning	3
Installation.....	3
Mounting	4
Electrical	5
Main Power.....	6
Transmitter Connections	6
Ethernet Connections	6
Adjustments.....	6
Storage and Installation Environment	6
Physical Dimensions	7
Specifications	8

SECTION 2 – SAFETY

Potential Electrical Hazards	9
------------------------------------	---

SECTION 3 – START-UP AND OPERATION

MS2510 Receiver Start-Up.....	11
Operation	12
Controls Operation.....	14
Title Screen	14
Main Screen	15
Setup Screen	17
Data Chart Screen.....	19
About Screen	20

SECTION 4 – MAINTENANCE

Fuse Replacement	21
------------------------	----

SECTION 5 – TROUBLESHOOTING

Troubleshooting Procedures.....	22
---------------------------------	----

SECTION 6 – RETURNING THE INSTRUMENT FOR REPAIR

Return Instructions	23
---------------------------	----

SECTION 7 – WARRANTY

Warranty	25
----------------	----

SECTION 8 – WIRING DIAGRAM

Wiring Diagram	26
----------------------	----

Section 1 - Introduction

RECEIVING THE INSTRUMENT

The MS2510 Receiver is carefully prepared for shipment to protect it during transit and to enable the user to install it with a minimum amount of reassembly.

Upon receipt, the instrument should be carefully inspected for transit damage. If damage is apparent, notify Metal Samples and the carrier for claims inspection.

UNPACKING

Open the package and remove the instrument carefully. The instrument contains a display screen. While removing, utmost care should be given to the display.

CLEANING

Clean the instrument thoroughly to remove any foreign material that may have accumulated during shipment.

INSTALLATION

Place the receiver instrument in a convenient location, preferably away from heat producing sources or direct sunlight.

Use the mounting brackets supplied with the instrument as shown in Figure 1.

MOUNTING




Figure 1 – Instrument Mounting

ELECTRICAL




Figure 2 – Connections

MAIN POWER

Connect the single phase main voltage 100 V to 240 V by means of supplied main cord. Local regulations must be considered before connecting it.

Note: In some cases, the instrument is shipped without a connector on the power cord. Each locality should inspect the power cord and install the proper connector if necessary. The connector should be installed in a properly grounded outlet for proper over current and earth fault protection.

TRANSMITTER CONNECTIONS

Connect the transmitter connections as below.

Positive Terminal - 1 (+)
Negative Terminal - 2 (-)
(See wiring diagram – Page 26.)

ETHERNET CONNECTIONS

If you are connecting the MS2510 to an Ethernet switch or Router, use a Straight RJ45 cable. If you are connecting to a PC, use a Crossover RJ45 cable. Before connecting the MS2510 to your local network please contact your network administrator for proper IP address configuration of the instrument.

Warning – A duplicated IP address may cause network failure at the installation site. Consult Network Administrator.

ADJUSTMENTS

The MS2510 Receiver functions must be adjusted and operated only by those authorized personnel who have read and who thoroughly understand the descriptions of the various control functions presented in this manual.

STORAGE AND INSTALLATION ENVIRONMENT

Protect the receiver instrument from mechanical stress, humidity, dust and thermal damage. Storage temperature is -20° C to +60° C. Operating temperature is 0° C to 50° C.

PHYSICAL DIMENSIONS




Figure 3 – Physical Dimensions

Overall Dimensions: 9.85" H x 11.73" W x 6.50" D

SPECIFICATIONS

WEIGHT	-	~4 lbs (~1.9 Kg)
DIMENSIONS	-	9.85" x 11.73" x 6.50" (25.02cm x 29.79cm x 16.51cm)
MOUNTING	-	Panel Mount / Rack Mount
OPERATING TEMP.	-	32° F to 122° F (0° C to 50° C)
POWER SUPPLY		
Voltage	-	100 – 240 V, 1 phase, 50/60 Hz
Current	-	< 2 Amps
SIGNAL		
Input	-	4 – 20 mA current loop
Voltage	-	24V DC
Input Impedance	-	250 Ohms
Fuse	-	100mA 250V

NETWORK

Use Crossover cable to connect the instrument directly to a PC.

Use Straight Cable to connect to the network switch, router...

Section 2 – Safety

Always follow these warnings and safety procedures:

Before attempting to operate or perform any service functions, all operators and service personnel should read this manual to become familiar with the complete operation of the instrument. Becoming familiar with all operating procedures will greatly reduce the possibility of accidents or injury.

ONLY QUALIFIED OPERATORS AND MAINTENANCE PERSONNEL THAT HAVE COMPLETE AND CORRECT KNOWLEDGE OF THE RECEIVER INSTRUMENT SHOULD PERFORM ALL OPERATIONS AND MAINTENANCE PROCEDURES.

POTENTIAL ELECTRICAL HAZARDS

!!DANGER!!

Do not touch electrically live components. Before performing any maintenance procedures, make sure that the main switch, located on the bottom of the instrument enclosure is in the “OFF” position.

Receiver instrument must be properly grounded.

Damaged electrical connections or wires should be replaced before power is applied.

All covers must remain securely in place when power is applied or electrical shock may result.

Always follow these electrical system safety procedures:

- Before servicing or troubleshooting procedures are performed, make sure that the electrical drawings for that area are up-to-date.
- Follow proper plant, regional and national safety procedures while servicing the electrical systems on this instrument.
- Remove all metal items, such as rings, metal necklaces and wrist watches. These are electrical hazards. Medical alert jewelry should be worn with caution.
- Use insulated tools when working on electrical equipment to reduce the possibility of shock.
- When troubleshooting with power activated, know the amount of voltage present in all areas before troubleshooting.
- Before working on any circuit, check the circuit with the proper tester to determine if any voltage is present.
- Be familiar with the proper handling of an electrical fire; keep carbon dioxide and dry powder fire extinguishers accessible at all times.
- Always use fuses of a smaller capacity than the safe capacity of the line or equipment it serves.

Section 3 – Startup & Operation

Warning - Ensure that the MS2510 receiver is connected properly.

MS2510 RECEIVER START-UP

If the MS2510 has not been used for an extended amount of time (overnight, weekend, or holiday), follow the procedure below to start the instrument:

1. Ensure the transmitter connections are connected properly to the MS2510 receiver unit.
2. Ensure the power cord is connected and power is turned on. The main switch is located under the instrument. The green light illuminates once the switch is on.
3. When the power is turned on, the instrument boots up and the Title screen appears for a short time. The display then changes to the Main screen which shows the metal loss and corrosion rate display.
4. After approximately a minute the display updates the current metal loss value.
5. Check the Probe life data on the Setup screen. If required, change the probe life according to the probe connected.

Probe Initialization Message

A Probe Initialization message will appear on the screen if the instrument loses the probe life data setting or if a new version of the program is installed. Pressing 'OK' on the message takes the display to the Setup screen. You may enter the right probe life using the pop-up keyboard on the screen.

OPERATION

The MS2510 instrument is a line powered current loop receiver that provides 24V DC to power a 2 wire 4-20 mA instrument loop and provides a display of the loop value in metal loss and calculated corrosion rate.

The corrosion rate time period can be set with different intervals of 48 hours, 7 days, 15 days and 30 days.

The Corrosion rate is calculated using a simplified algorithm that calculates every 30 minutes based on the metal loss change over the previous 48 hours to 30 days according to the setting.

The metal loss values are stored in the instrument's internal memory with a time stamp. These values can be used for metal loss analysis at any given time.

The built-in web server also can be used to monitor the display on a remote computer through a network.

Output

The Metal loss is calculated using one of the following formulas.

$$\text{Metal Loss (mils)} = \frac{(I_L - 4)}{16} * \text{ProbeLife}$$

$$\text{Metal Loss } (\mu\text{m}) = \frac{(I_L - 4)}{16} * \text{ProbeLife} * 25.4$$

Where:

I_L = Loop Current in mA

ProbeLife = Usable portion of probe element thickness in mils (See Table 1.)

TABLE 1 : PROBE LIFE AND ELEMENT ID

Element Type	Element Thickness	Probe Life	Element Identifier
Wire Loop	40 mil	10 mil	WR 40
	80 mil	20 mil	WR 80
Tube Loop	4 mil	2 mil	TU 04
	8 mil	4 mil	TU 08
Strip Loop	4 mil	1 mil	SL 04
	8 mil	2 mil	SL 08
Cylindrical	10 mil	5 mil	CT 10
	20 mil	10 mil	CT 20
	50 mil	25 mil	CT 50
Spiral Loop	10 mil	5 mil	SP 10
	20 mil	10 mil	SP 20
Flush(Small)	4 mil	2 mil	FS 04
	8 mil	4 mil	FS 08
	20 mil	10 mil	FS 20
Flush (Large)	10 mil	5 mil	FL 10
	20 mil	10 mil	FL 20
	40 mil	20 mil	FL 40
Surface Strip	10 mil	5 mil	SS 10
	20 mil	10 mil	SS 20
	40 mil	20 mil	SS 40


CONTROLS OPERATION

TITLE SCREEN



The Title screen is the first screen displayed when power is activated and after the instrument boots up.

MAIN SCREEN



METAL LOSS

Display indicates the active metal loss data in the selected unit (mils / microns).

CORROSION RATE

Display indicates the active Corrosion rate in the selected unit (mils / microns) per year. The corrosion rate is calculated based on the metal loss over the period of time which is set through the Setup screen.

After the power is turned on the first time or after a probe is changed out, the corrosion rate will begin to calculate after 48 hours and will display a value at that time even if the instrument is set to a value other than the "48 hours" setting. If the set value is other than "48 hours", once the set value time is reached, the instrument will start calculating the corrosion rate according to the set period.

LIVE DATA

This graph window displays the live data from the transmitter in metal loss value.

SETTINGS



Press the Settings button to display the Setup screen

DATA CHART




Press the Chart button to view the Data Chart screen

INFORMATION



Press the Information button to display the About screen

SETUP SCREEN



DISPLAY UNIT

Press the 'Display Unit' button to change the display units of the metal loss and corrosion rate as mils or microns on the Main screen.

CALCULATION PERIOD

This selection unit is for calculating the corrosion rate per year based on the set time. This can be selected as 48 Hours, 7 Days, 15 Days or 30 Days.

PROBE LIFE

Set the Probe life according to the probe used on the field. This setting should be in mils.

HOME



Press the Home button to display the Main screen

MAINTENANCE



Not Applicable.

DATA CHART




Press the Chart button to display the Data Chart screen

INFORMATION



Press the Information button to display the About screen

DATA CHART SCREEN



YEAR

Press the 'Year' entry box and enter the year for which the metal loss data should be charted.

MONTH

Select the month to view the metal loss data for the respective month or select 'ALL' to view the data for the whole year.

HOME



Press the Home button to display the Main screen

ABOUT SCREEN



0000

152 Metal Samples Rd.
Munford, AL 36268
Tel # (001)256-358-4202
Fax # (001)256-358-4515
eMail : msc@alspi.com
www.metalsamples.com



HOME




Press the Home button to display the Main screen

Section 4 - Maintenance

Fuse Replacement

Replace the main fuse by following the procedure below.

- 1) Turn off the main Power switch
- 2) Remove the Single Phase power cord connected to the instrument.



- 3) Using a small screwdriver or fuse drawer remover, push the tab shown in the above picture and pull the fuse drawer out. One spare fuse will be provided in the fuse drawer. Remove the blown fuse and replace with the spare. Press the fuse drawer inside and ensure it is properly locked in its position.
- 4) Connect the main cord and turn on the main power.

Section 5 – Troubleshooting

Fault messages display on the status window to identify the location and type of fault that has occurred.

This troubleshooting section addresses common instrument problems, possible causes and recommended solutions.

IMPORTANT: It is not the intent of this manual to provide a highly detailed breakdown of all possible problems that may be encountered while using this instrument.

Warning - If a problem cannot be easily corrected, contact Metal Samples for help.

<u>PROBLEM</u>	<u>POSSIBLE CAUSE</u>	<u>SOLUTION</u>
No Display	Power is not activated.	Check the main supply and ensure the switch in the “On” position.
	Blown Fuse	Replace the fuse.
	Display defective	Contact Metal Samples.
No Metal Loss Value Display	Current loop wires loose	Check and properly connect the current loop wires.
	Current loop wires polarity	Check the polarity of the connected current loop wires.
	24V missing	Check 24V on current loop wires. Contact Metal Samples.

Section 6 – Returning the Instrument for Repair

If it is necessary to return any Metal Samples instrument for repair, the following procedure is recommended to ensure the fastest possible repair and return cycle. You may contact Metal Samples to verify that returning the instrument is necessary.

1. If possible, pack the instrument in the original shipping carton. If the original carton is not available, pack the instrument in a rigid cardboard or wood carton. Surround the instrument with a minimum of three inches of resilient packing material such as foam rubber or shredded newspaper.
2. Ship the instrument prepaid via air freight or air express to:

**Metal Samples
152 Metal Samples Rd.
Munford, AL 36268**

3. Contact Metal Samples by **telephone (256) 358-4202, fax (256) 358-4515, or e-mail msc@alspi.com** and tell them:
 - a. the name of the shipping company used for returning the instrument
 - b. the estimated time of arrival
 - c. the tracking number for the package
4. When the instrument is packed, include a copy of the form on the next page, filled in as required to expedite the repairs.

Return Form

Use this form when returning instruments to Metal Samples for repair. Please fill in all known information. Enclose a copy of the completed form with the instrument.

1. Check one:

- Repair this instrument under warranty.
 Repair this instrument regardless of problem or cost of repair.
 Inspect the instrument and advise the customer of the approximate cost of repairs if the instrument is not covered under warranty. (Note: This procedure may delay the return of the instrument to you.)

2. Instrument Identification:

Instrument Model #: _____

Serial #: _____

Date of Purchase: _____

Company's Purchase Order # for Original Sale: _____

3. Return the Instrument to:

Company Name: _____

Address/Location: _____

Phone #: _____

4. Description of Trouble: (a clear description of the problem may shorten repair time).

6. Urgency of Repairs: _____

Section 7 – Warranty

Metal Samples warrants that any part of their corrosion rate instruments and accessories which proves to be defective in material or workmanship within one year of the date of original shipment to Purchaser will be repaired or replaced, at the option of Metal Samples, free of charge. This warranty does not cover (1) probe assemblies, (2) items expendable in nature, or (3) items subject to damage from normal wear, misuse or abuse, or failure to follow use and care instructions.

All damaged items are to be shipped at Purchaser's expense to and from Metal Samples. Metal Samples shall have the right to final determination as to the existence and cause of the defect.


The foregoing shall constitute the sole and exclusive remedy of any purchaser of Metal Samples products for breach of warranty and is exclusive and in lieu of all other warranties, expressed, implied or statutory, including the implied warranties of merchantability and fitness. In no event shall Metal Samples be liable for special or consequential damages or for any delay in the performance of this warranty due to causes beyond its control.

Orders or requests for additional information should be addressed to:

**Metal Samples
152 Metal Samples Rd.
Munford, AL 36268
Telephone: (256) 358-4202
Fax: (256) 358-4515
E-mail: msc@alspi.com**

The technical information and suggestions contained herein are believed to be reliable, but they are not to be construed as warranties since conditions of use are beyond our control.

Section 8 – MS2510 Wiring Diagram



Typical Wiring Diagram.

Note: This wiring diagram is not suitable for hazardous area installation. Please see the MS2500E manual for hazardous area installation wiring.